Risk Assessment
Adventure Playground

Hazard	Who could be harmed/ risk level	Control Measures	Further Action
Falling from height	Participants Likelihood- 2 Consequence – 2/3	Impact absorbent safety bark installed to all equipment where there is critical fall height. Participants to wear sensible footwear. The number of participants on any one piece of equipment must be limited to ensure safety and overcrowding.	There must be adult supervision in the playground at all times.(warning signs in place) Under no circumstances must the playgrounds be used unsupervised. *Adult leaders to be made aware of the risk assessment and rules for the adventure playground.
Equipment failure	Participants Likelihood- 2 Consequence – 2/3	All equipment and surfaces to be checked by ground maintenance team. Any equipment or damage will result in that particular apparatus being closed for use until rectified. All equipment conforms to BS/EN1176 (playground equipment surfacing and installation). All defects reported immediately to the committee for rectification.	System of checks and log book to be set up.
General	All Participants	The bark surface to be topped up as necessary. Equipment should not be used when underfoot conditions are wet causing hands or feet to slip.	Adult supervisor must make this assessment

Likelihood- 1- unlikely 2- possible 3 quite possible 4- likely 5- very likely
Consequence 1- no injury 2 – slight injury 3- injury over 3 days 4 – death 5- multiple death

Current control measures - adult supervision at all times
Are these adequate? Yes **What other measures are necessary?** None **Monitoring -**accident book, equipment checked and logged monthly.

Assessor Date 8 .6.16 Reviewed by Jess Green Date January 2025